AD-A074 404 NAVY ELECTRONICS LAB SAN DIEGO CA F/G 17/1
CALIBRATION DATA ON SONAR DOME PAINTS.(U)
JAN 63

UNCLASSIFIED NL



1 OF 1
AD A074404

END
DATE FILMED
10-79
DDC


1.0
1.1
1.25
1.4
1.6
2.8
3.2
3.6
4.0
2.5
2.2
2.0
1.8
MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

U.S. NAVY ELECTRONICS LABORATORY
Transducer Calibration Facility
San Diego 52, California

CALIBRATION DATA

on

SONAR DOME PAINTS

(11) 11 Jan 63

(12) 42p.

253 550

MOST Project

U.S. NAVY ELECTRONICS LABORATORY
Transducer Calibration Facility
San Diego 52, California

Approved: Delores A. Pierce
Miss Delores A. Pierce
Head - Data Reduction

TABLE of CONTENTS

* Indicates forced drying of the particular coat of paint with hot air at 120° F ± 10° F for one hour. Otherwise all coatings air dried at ambient indoor temperatures.

** All panels coated similarly front and back except as noted.



DIAGRAM of MOUNTING ARRANGEMENT

Measured at Sweetwater
Calibration Station
19 December 1962

U.S. NAVY ELECTRONICS LABORATORY
Transducer Calibration Facility
San Diego 52, California

EFFECT of TEST PANELS No. 1, 2, 3 and 4 (COATED and UNCOATED)* on SOUND FIELD

Temperature: 13.3°C
Depth: 3.90 meters

See Diagram, Page 1, for mounting arrangement.

* As there was no measureable difference between these panels they are shown as 1 curve.



D3769-2 R11,12,15 & 16


DIRECTIVITY PATTERN
U. S. NAVY ELECTRONICS LABORATORY
TRANSDUCER CALIBRATION FACILITY
SAN DIEGO, CALIFORNIA
Sweetwater Station
Test Panel No. 1
(UNCOATED)
19 December 1962
Panel Removed
With Panel*
0°
30°
20°
10°
350°
340°
330°
40
50
60
70
80
90
100
110
120
130
140
160°
170°
180°
190°
200°
210°
Frequency 14 kc
0° is normal to Panel
Rotate
Depth 3.00 meters
Test Distance 1.25 meters
Temperature 13.3 C
D3766-2 A13
* See Diagram, Page 1, for mounting arrangement.
Scale 1 db per radial division
CODEX BOOK COMPANY, INC. NORWOOD, MASSACHUSETTS.
PRINTED IN U.S.A.
NO. 3124 POLAR CO-ORDINATE.


DIRECTIVITY PATTERN
U. S. NAVY ELECTRONICS LABORATORY
TRANSDUCER CALIBRATION FACILITY
SAN DIEGO, CALIFORNIA
Sweetwater Station
Test Panel No. 2 coated with SONAR DOME PAINTS
19 December 1962
Panel Removed
With Panel*
0° is normal to Panel
Rotate
Frequency 14 Kc
Depth 3.90 meters
Test Distance 1.25 meters
Temperature 13.3 C
03769-2 R10
* See Diagram, Page 1, for mounting arrangement.
Scale 1 db per radial division
CODEX BOOK COMPANY, INC. NORWOOD, MASSACHUSETTS. PRINTED IN U.S.A.
NO. 3124 POLAR CO-ORDINATE.
4

Measured at Sweetwater
Calibration Station
18 December 1962

U.S. NAVY ELECTRONICS LABORATORY
Transducer Calibration Facility
San Diego 52, California

EFFECT of TEST PANELS No. 5, 6, 7 and 8 (COATED)* on SOUND FIELD

Temperature: 13.3°C
Depth: 3.90 meters

See Diagram, Page 1, for mounting arrangement.

* As there was no measureable difference between these panels they are shown as 1 curve.



D3769-1 R1,4,5 & 8


DIRECTIVITY PATTERN
U S NAVY ELECTRONICS LABORATORY
TRANSDUCER CALIBRATION FACILITY
SAN DIEGO, CALIFORNIA
Sweetwater Station
Test Panel No. 3 coated
with SONAR DOME PAINTS
18 December 1962
Panel Removed
-with Panel*
Frequency 3 Kc
te is normal to Panel
Rotate
Depth 3.00 meters
Test Distance 1.25 meters
Temperature 13.3 C
D 3769-1 R3
* See Diagram, Page 1, for mounting arrangement.
Scale, 1 db per radial division
30° 330°
20° 340°
10° 350°
0°
350° 10°
340° 20°
330° 30°
40° 320°
50° 310°
60° 300°
70° 290°
80° 280°
90° 270°
100° 260°
110° 250°
120° 240°
130° 230°
140° 220°
150° 210°
160° 200°
170° 190°
180°
190° 170°
200° 160°
210° 150°
320° 40°
310° 50°
300° 60°
290° 70°
280° 80°
270° 90°
260° 100°
250° 110°
240° 120°
230° 130°
220° 140°
50
40
30
20
10
0
CODEX BOOK COMPANY, INC. NORWOOD, MASSACHUSETTS.
PRINTED IN U.S.A.
NO. 3124 POLAR CO-ORDINATE.


DIRECTIVITY PATTERN
U. S. NAVY ELECTRONICS LABORATORY
TRANSDUCER CALIBRATION FACILITY
SAN DIEGO, CALIFORNIA
Sweetwater Station
Test Panel No. 6 coated
with SONAR DOME PAINTS
18 December 1962
Panel removed
With Panel*
0° is normal to Panel
Rotate
Frequency: 3 Kc
Depth 3.90 meters
Test Distance: 1.25 meters
Temperature 13.3 C
D 3760-1 R6
* See Diagram, Page 1, for mounting arrangement.
Scale: 1 db per radial division
CODEX BOOK COMPANY, INC. NORWOOD, MASSACHUSETTS.
PRINTED IN U.S.A.
NO. 3124 POLAR CO-ORDINATE


DIRECTIVITY PATTERN
U. S. NAVY ELECTRONICS LABORATORY
TRANSDUCER CALIBRATION FACILITY
SAN DIEGO, CALIFORNIA
Sweetwater Station
Test Panel No. 7 coated
with SONAR DOME PAINTS
18 December 1962
Panel Removed
With Panel*
0° is normal to Panel
Rotate
Frequency 3 Kc
Depth 3.90 meters
Test Distance 1.25 meters
Temperature 13.3 °C
D 3769-1 R7
* See Diagram, Page 1, for mounting arrangement.
Scale 1 db per radial division
30° 330°
20° 340°
10° 350°
0
350° 10°
340° 20°
330° 30°
40° 320°
50° 310°
60° 300°
70° 290°
80° 280°
90° 270°
100° 260°
110° 250°
120° 240°
130° 230°
140° 220°
150° 210°
160° 200°
170° 190°
180°
190° 170°
200° 160°
210° 150°
320° 40°
310° 50°
300° 60°
290° 70°
280° 80°
270° 90°
260° 100°
250° 110°
240° 120°
230° 130°
220° 140°
40
30
20
10


DIRECTIVITY PATTERN
U. S. NAVY ELECTRONICS LABORATORY
TRANSDUCER CALIBRATION FACILITY
SAN DIEGO, CALIFORNIA
Sweetwater Station
Test Panel No. 8 coated
with SONAR DOME PAINTS
18 December 1962
Panel Removed
With Panel*
0° is normal to Panel
Rotate
Frequency: 3 Kc
Depth 3.90 meters
Test Distance: 1.25 meters
Temperature 13.3 C
D3769-1 R3
*See Diagram, Page 1, for mounting arrangement.
Scale: 1 db per radial division
CODEX BOOK COMPANY, INC. NORWOOD, MASSACHUSETTS. PRINTED IN U.S.A.
NO. 3124 POLAR CO-ORDINATE.